

Scope of Consultancy Service:

1. Building Inspection and Condition Appraisal
2. Survey Report for Expert Witness, Valuation Report for Fire Insurance Reinstatement

Project 項目	Scope of Consultancy Service 服務範圍	Client 客戶
2005		
Ling Liang Church Ma On Shan, N.T. 新界馬鞍山靈糧堂	New Church Pre-sale Title Feasibility Study 新建教堂發展可行性研究報告	Ling Liang Church Ma On Shan 馬鞍山靈糧堂
2006		
Chong Ming Mansion, North Point, Hong Kong 香港北角昌明洋樓	Feasibility Study Report 入則申請可行性研究報告	The Incorporated Owners 業主立案法團
Harbour Centre Tower 2, Hung Hom, Kowloon 九龍紅磡海港中心二期	Feasibility Study Report 處所更改用途申請可行性研究報告	Jebesen Co. Ltd. 捷成洋行
2007		
Sceneway Garden, 8 Sceneway Road, Lam Tin, Kowloon 九龍藍田匯景花園	Feasibility Study Report 處所更改用途申請可行性研究報告	Goodwell Property Management Ltd. 高衛物業管理有限公司
Venus Industrial Building, Tai Lin Pai Road, Kwai Chung 新界葵涌大連排道金星工業大廈	Feasibility Study Report 入則申請可行性研究報告	Metalor Technologies (Hong Kong) Limited 美泰樂科技(香港)有限公司
Kwai Shun Industrial Centre 葵信工業中心	Feasibility Study Report 處所更改用途申請可行性研究報告	ISS EastPoint Facility Services Ltd.
2008		
Tower 11, 55/Fl., Phase III, Caribbean Coast, Tung Chung, Lantau 香港東涌映園灣悅瀟軒11座55樓	Feasibility Study Report 處所更改用途申請可行性研究報告	LLS Design Limited
Mita Centre, No. 552-566 Castle Peak Road, Kwai Chung, N.T. 新界葵涌段青山道 552-566 號美達中心	Feasibility Study Report 處所更改用途申請可行性研究報告	Jones Lang LaSalle Management Services Ltd. 仲量聯物業管理有限公行
5/F, Venus Industrial Building, 45-51 Tai Lin Pai Road, Kwai Chung, N.T. 新界葵涌大連排道45-51號金星工業大廈五樓	Feasibility Study Report 處所更改用途申請可行性研究報告	Metalor Technologies (HK) Limited 美泰樂科技香港有限公司
N0 2-22 Mount Butler Drive, Jardine's Lookout, H.K. 香港渣甸山 畢拉山徑2-22 號	Feasibility Study Report 處所更改用途申請可行性研究報告	Eternal Year Property Services Ltd 永年物業管理有限公司
2009		
G/F, 1/F-6/F & Roof of Nos. 76 & 76A of Yue Man Square, Nos. 437-449 Kwun Tong Road & Nos.64-76 Yue Man Square, Kwun Tong, Kowloon 九龍觀塘觀塘道437-449 號裕民坊地下、一樓至六樓和天台	Feasibility Study Report 處所更改用途申請可行性研究報告	Yuen Fung Investment Co Ltd c/o Memfus Wong Surveyors Ltd
1/F, Lung Wah Court at 28-30 Ko Shan Road, Tokwawan, Kowloon 九龍土瓜灣高山道 28-30 號龍華閣一樓	Feasibility Study Report 處所更改用途申請可行性研究報告	Pentecostal Church of H.K. Holy Mountain Church\ 竹園區神召會高山堂
Flat B, 11/F, Block 12, Villa Rhapsody, Symphony Bay, 533 Sai Sha Road, Ma On Shan 新界西沙路 533 號帝琴灣凱琴居12座11樓E室	Feasibility Study and Condition Survey 處所更改用途申請可行性研究報告	B&M Design Ltd

Scope of Consultancy Service:

1. Building Inspection and Condition Appraisal
2. Survey Report for Expert Witness, Valuation Report for Fire Insurance Reinstatement

Project 項目	Scope of Consultancy Service 服務範圍	Client 客戶
94-96 Robinson Road, Hong Kong 香港羅便臣道94 - 96 號	Feasibility Study Report 處所更改用途申請可行性研究報告	Ms Amy Ng 吳小姐
Galaxia, No. 3 Lung Poon Street, Diamond Hill, Kowloon 九龍鑽石山龍蟠街3號星河明居	Feasibility Study and Condition Survey 處所更改用途申請可行性研究報告	ISS Eastpoint Property Mgt Ltd 置邦興業有限公司
2010		
Shun Sing Mansion No. 466, Des Voeux Road, Hong Kong 西環德輔道西466號	Feasibility Study Report 入則申請可行性研究報告	Mr. Lee 李先生
Flat E&F, 30/F, Tower 2, Sausalito, Ma On Shan 馬鞍山 嵐岸2座 30樓, E及F室	Feasibility Study Report 入則申請可行性研究報告	NWB-Concept Limited
7/F to 27/F Kinwick Centre at 32 Hollywood Road Central 荷李活道32號 建業榮基中心7樓至27樓	Feasibility Study Report 入則申請可行性研究報告	Jones Lang LaSalle Mgt. Services Ltd. 仲量聯物業管理有限公司
Wai Kiu College 17 Wai Chi Street, Shek Kip Mei, Kowloon 偉智街17 號 惠僑英文中學	Feasibility Study Report 入則申請可行性研究報告	Zhongtai Decoration Co., Ltd.
2011		
Katherine House, 53-55 Chatham Road South, Tsim Sha Tsui 尖沙咀漆咸道南53-55號嘉芙中心	Feasibility Study Report 入則申請可行性研究報告	Jones Lang LaSalle Property Management Ltd. 仲量聯行物業管理有限公司
Nos. 42 Wo Yi Hop Road, Kwai Chung, N.T. 新界葵涌和宜合道42號	Feasibility Study Report 入則申請可行性研究報告	The Yuen Yuen Institute No.1 Secondary School 玄園學院第一中學
2013		
Tsuen Wan Chinese Cemetery, Wing Shun Street, Kwai Chung, N.T. 葵涌永順街荃灣華人永遠墳場	"Barrier Free Access" Feasibility Study Report "暢通無阻通道"可行性研究報告	B.M.C.P.C. 華人永遠墳場管理委員會